

B8 8100 Bypass shocks are corner specific. This instruction is for both rear left (driver) 25-305258 & rear right (passenger) 25-305265 B8 8100 shocks.

### **IMPORTANT! READ THIS FIRST!**

Installation of shock absorbers requires special tools and expert knowledge. Accordingly, installation of all BILSTEIN products must be performed by a professional automotive suspension technician.

When replacing other brands, BILSTEIN shock absorbers should always be installed as a set. All BILSTEIN products must only be used for the specific, intended application as indicated in the application guide. Any use of any BILSTEIN product other than for its intended use may result in serious bodily injury or death.

Always use a chassis hoist for the installation of BILSTEIN products and make certain that the raised vehicle is securely attached to the hoist and/or supported to prevent the vehicle from slipping, falling, or moving during the installation process.

If you install any BILSTEIN product without the necessary special tools, expertise, and chassis hoist, you may subject yourself to the risk of serious bodily injury or death.

BILSTEIN shock absorbers are gas-filled and are highly pressurized.

- Never place any BILSTEIN product in a vise or use a clamp on any BILSTEIN product.
- Never apply heat near any BILSTEIN product.
- Never attempt to open or repair any BILSTEIN product, in order to prevent serious bodily injury or death.

Any attempt to misuse, misapply, modify, or tamper with any BILSTEIN suspension product voids any warranty and **may result in serious bodily injury or death.** 

While installing any BILSTEIN product:

- Do not use impact tools for loosening or tightening fasteners, because this may destroy the screw threads.
- Self-locking fasteners must only be used **once**!
- Reuse original equipment components only if they are in good condition, otherwise replace them with new components.
- Never remove the slight film of oil on the piston rod and seal.
- All mounting fasteners for shocks and struts must be securely tightened before tension is
  placed on the suspension system, unless otherwise specified in the manufacturer's service
  manual or in this instruction.

After installing any BILSTEIN product:

- The suspension caster and camber must be checked and/or adjusted to comply with the vehicle manufacturer's specifications.
- The (load dependent) brake compensator and the anti-lock brake system must be checked and/or reset to comply with the vehicle manufacturer's specifications.
- The headlight aim must be checked and adjusted.

### **IMPORTANT!!!**

Created: 07.01.20

This Bilstein product may or may not be compatible with non-Bilstein aftermarket products and/or vehicle modifications. It is the responsibility of the professional automotive suspension technician performing the installation to identify any non-OEM components and/or modifications on the vehicle that may interact with the suspension system. These must be evaluated for any potential physical static or dynamic interference with and/or effect on the function of this Bilstein product.



B8 8100 bypass shocks feature a proprietary BILSTEIN zinc plated finish. This finish must be serviced in order to maintain its luster. Particularly in moist climates, a protective coating, such as a wax or lubricating oil should be periodically applied to prevent tarnishing. This finish is not covered under warranty.

It is normal to hear a slight audible clicking noise during compression and rebound strokes in the B8 8100 bypass shocks, most notably during low velocity events. This is due to the internal check pistons opening and closing to create the externally adjustable compression and rebound zones.

BILSTEIN 8100 Series Reservoir Shock Absorbers are designed to fit your vehicle's original shock mounts with no modifications. With the exception of reservoir placement, the 8100 Series shocks are installed in the same manner as a standard replacement shock.

- **A.** Remove the existing rear shocks from the vehicle following all procedures in the vehicle manufacturer's service manual.
- **B.** Position reservoir for the driver side as depicted in Figures 1 and 2. Position reservoir for passenger side as depicted in Figures 3 and 4. The reservoir should be placed in the location pictured below.







Figure 2 - Rear Driver Side







Figure 3 - Rear Passenger Side

Figure 4 - Rear Passenger Side

- **C.** Install the complete shock/reservoir assemblies on the vehicle. All original fasteners can be reused.
- **D.** Take the secondary schrader cap assembly provided and screw it into the bottom reservoir cap for both sides as shown in Figure 5. Torque it to 13 lb•ft (17.5 N•m).




Figure 5



- **E.** If a chassis hoist has been used, be sure to lower the vehicle such that its full weight is on the suspension prior to fully tightening the fasteners.
- **F.** Carefully check for any possible interference between the reservoirs and any other components on the vehicle. The reservoir mounting locations depicted herein are appropriate for most Jeep JT vehicles, however, some wheel/tire and or lift kit combinations may create interference problems. It is the responsibility of the installer to determine if there is any potential for interference.
- **G.** Tighten all remaining fasteners to the vehicle manufacturer's service manual torque specifications.

Installation is complete.

B8 8100 bypass shocks allow the user to tune the damping for the best possible ride quality of their vehicle. The shocks offer multiple zones of compression and rebound damping, depending upon the bypass configuration. The factory setting is:

**Rebound** – 6 full turns out from fully closed **Compression** – 7 full turns out from fully closed \*note: 4 clicks equal 1 full turn

The bypass adjusters allow adjustment up to 10 full turns out from fully closed.

#### B8 8100 bypass adjustment procedure:

Rotate the blue and red adjuster knobs to make the desired adjustment.

TURN IN (Clockwise) the adjuster knob to INCREASE damping

TURN OUT (Counter Clockwise) the adjuster knob to DECREASE damping

### B8 8100 bypass service:

For service of your B8 8100 bypass shocks, please contact:

THYSSENKRUPP BILSTEIN OF AMERICA

Toll Free: 1-800-537-1085

bilsteinus.com

Created: 07.01.20